Oil Field Environmental Incident Summary

Incident: 20150903093802 Date/Time of Notice: 09/03/2015 09:38 Responsible Party: WISCO, INC. WISCO, INC. Well Operator: Well Name: WISCO #1 Field Name: ROUND PRAIRIE Well File #: 90247 **Date Incident: 9/2/2015** Time Incident: 18:45 Facility ID Number: 700090-01 County: WILLIAMS Twp: 154 Rng: 104 Sec: 26 Qtr: **Location Description:** Submitted By: Jim Weber Received By: Contact Person: Jim Weber 4903 2ND AVE WEST WILLISTON, ND 58802 General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil Distance Nearest Occupied Building: 2 Mile Distance Nearest Water Well: 2 Mile Type of Incident Tank Overflow Release Contained in Dike Yes - Within Dike Reported to NRC: Yes **Spilled** Units Recovered Units Followup **Units** Oil **Brine Barrels** Other 12 **Barrels** 12 **Description of Other Released Contaminant:** Oil and Water Inspected: Written Report Received: Clean Up Concluded: Risk Evaluation: None Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

Hydro vac was called to come out and wash down the tanks and suck all free fluids and contaminated soil. We are installing and air conditioning unit in the control room where the electrical panel is for the disposal pump. We are also creating an SOP on the off load procedure at the SWD for when hot weather is upon us and tanks are at high level.

Wastes Disposal Location: All recovered wastes will be disposed of at our PRD which is on location.

Agencies Involved:

Updates

Date: 9/3/2015 Status: Reviewed; O&G Lead

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank overflow, remained on location according to the report. NDIC retains oversight.